

Information on Tube wells, Hand pumps and Electric pumps

Report : Yearly

District : Amravati

Reporting Year : 2010-11

Taluka	Current Year					Year Ending		Reference Year
	Total BoreWells (Numbers)	Of Which High Capacity BoreWells (Numbers)	Successful BoreWells (Numbers)	Installed HandPumps (Numbers)	Installed ElectricPumps (Numbers)	Working HandPumps (Numbers)	Working ElectricPumps (Numbers)	
1	2	3	4	5	6	7	8	9
Dharni	4	N.A.	3	3	N.A.	541	12	2010-11
Chikhaldara	9	N.A.	7	6	1	352	6	2010-11
Anjangaon Surji	11	3	11	10	1	243	28	2010-11
Achalpur	40	14	40	39	N.A.	417	35	2010-11
Chandurbazar	22	6	22	19	1	284	30	2010-11
Morshi	1	N.A.	N.A.	N.A.	N.A.	265	23	2010-11
Warud	N.A.	N.A.	N.A.	N.A.	N.A.	343	14	2010-11
Teosa	8	N.A.	6	6	N.A.	365	27	2010-11
Amravati	10	2	8	5	1	445	21	2010-11
Bhatkuli	23	6	23	19	3	160	17	2010-11
Daryapur	12	4	12	12	N.A.	42	6	2010-11
Nandgaon-Khandeshwar	18	2	13	12	1	655	23	2010-11
Chandur Railway	6	N.A.	5	5	N.A.	352	10	2010-11
Dhamangaon Railway	12	1	10	9	N.A.	547	14	2010-11
Total	176	38	160	145	8	5011	266	

Source :

'Sub Engineer (Mech.) Mechanical Section, Zilla Parishad, District Ground Water Survey Agency, Water Supply Division Zilla Parishad / Municipal Council/ Municipal Corporation'

Navigation Path :

www.mahasdb.maharashtra.gov.in > Home > Amravati > Irrigation And Flood Control > Reports

This report should be updated within 2 months after completion of Reporting period
Data as on May 9, 2013 on SDB