

**Information on Tube wells, Hand pumps and Electric pumps**

District : Chandrapur

Report : Yearly  
Reporting Year : 2010-11

Taluka	Current Year					Year Ending		Reference Year
	Total BoreWells (Numbers)	Of Which High Capacity BoreWells (Numbers)	Successful BoreWells (Numbers)	Installed HandPumps (Numbers)	Installed ElectricPumps (Numbers)	Working HandPumps (Numbers)	Working ElectricPumps (Numbers)	
1	2	3	4	5	6	7	8	9
Warora	47	16	43	41	2	544	22	2010-11
Chimur	65	15	65	63	2	998	8	2010-11
Nagbhir	51	14	50	50	0	918	22	2010-11
Brahmapuri	30	1	30	30	0	765	12	2010-11
Sawali	34	10	34	34	0	740	3	2010-11
Sindewahi	30	9	29	29	0	687	10	2010-11
Bhadravati	45	7	45	45	0	499	15	2010-11
Chandrapur	48	11	48	48	0	679	21	2010-11
Mul	17	5	17	17	0	585	4	2010-11
Pombhurna	6	1	5	5	0	330	1	2010-11
Ballarpur	14	7	14	14	0	301	12	2010-11
Korpana	37	5	27	27	0	783	6	2010-11
Jiwati	19	6	10	10	0	365	2	2010-11
Rajura	18	12	18	18	0	506	14	2010-11
Gondpipri	11	6	10	10	0	387	3	2010-11
<b>Total</b>	<b>472</b>	<b>125</b>	<b>445</b>	<b>441</b>	<b>4</b>	<b>9087</b>	<b>155</b>	

Source :

'Sub Engineer (Mech.) Mechanical Section, Zilla Parishad, District Ground Water Survey Agency, Water Supply Division Zilla Parishad / Municipal Council/ Municipal Corporation'

Navigation Path :

www.mahasdb.maharashtra.gov.in > Home > Chandrapur > Irrigation And Flood Control > Reports

This report should be updated within 2 months after completion of Reporting period

Data as on May 9, 2013 on SDB