

Information regarding Irrigation by Wells

Report : Yearly

District : Gadchiroli

Reporting Year : 2010-11

		Placed On in use Wells			
Taluka	Total Irrigated Wells (Number)	Diesel Pump (Number)	Electric Pump (Number)	Irrigated Wells not in Use (Number)	Reference Year
1	2	3	4	5	6
Desaiganj (Vadasa)	239	110	N.A.	43	2010-11
Armori	770	150	N.A.	211	2010-11
Kurkheda	1353	330	N.A.	110	2010-11
Korchi	413	122	N.A.	27	2010-11
Dhanora	847	29	N.A.	160	2010-11
Gadchiroli	983	285	N.A.	131	2010-11
Chamorshi	602	309	N.A.	181	2010-11
Mulchera	1140	25	N.A.	10	2010-11
Etapalli	465	25	N.A.	39	2010-11
Bhamragad	256	53	N.A.	51	2010-11
Aheri	216	155	N.A.	45	2010-11
Sironcha	161	26	N.A.	67	2010-11
Total	7445	1619	N.A.	1075	

Source :

'Commissionerate of Agriculture, GoM, Superintendant Of Land Record Office, Irrigation Department, Zilla Parishad, Tahsildar'

Navigation Path :

www.mahasdb.maharashtra.gov.in > Home > Gadchiroli > Irrigation And Flood Control > Reports

This report should be updated within 2 months after completion of Reporting period
Data as on May 9, 2013 on SDB