

Information on Tube wells, Hand pumps and Electric pumps

District : Gadchiroli

Report : Yearly
Reporting Year : 2010-11

Taluka	Current Year					Year Ending		Reference Year
	Total BoreWells (Numbers)	Of Which High Capacity BoreWells (Numbers)	Successful BoreWells (Numbers)	Installed HandPumps (Numbers)	Installed ElectricPumps (Numbers)	Working HandPumps (Numbers)	Working ElectricPumps (Numbers)	
1	2	3	4	5	6	7	8	9
Desaiganj (Vadasa)	0	0	0	0	0	266	2	2010-11
Armori	0	0	0	0	0	764	12	2010-11
Kurkheda	0	0	0	0	0	639	11	2010-11
Korchi	16	7	16	16	0	439	3	2010-11
Dhanora	0	0	0	0	0	764	4	2010-11
Gadchiroli	0	0	0	0	0	741	3	2010-11
Chamorshi	0	0	0	0	0	1353	4	2010-11
Mulchera	0	0	0	0	0	486	0	2010-11
Etapalli	0	0	0	0	0	729	3	2010-11
Bhamragad	0	0	0	0	0	341	0	2010-11
Aheri	50	22	49	49	0	777	2	2010-11
Sironcha	12	7	12	12	0	371	2	2010-11
Total	78	36	77	77	0	7670	46	

Source :

'Sub Engineer (Mech.) Mechanical Section, Zilla Parishad, District Ground Water Survey Agency, Water Supply Division Zilla Parishad / Municipal Council/ Municipal Corporation'

Navigation Path :

www.mahasdb.maharashtra.gov.in > Home > Gadchiroli > Irrigation And Flood Control > Reports

This report should be updated within 2 months after completion of Reporting period
Data as on May 9, 2013 on SDB