

**Information on Tube wells, Hand pumps and Electric pumps**

District : Hingoli

Report : Yearly  
Reporting Year : 2010-11

Taluka	Current Year					Year Ending		Reference Year
	Total BoreWells (Numbers)	Of Which High Capacity BoreWells (Numbers)	Successful BoreWells (Numbers)	Installed HandPumps (Numbers)	Installed ElectricPumps (Numbers)	Working HandPumps (Numbers)	Working ElectricPumps (Numbers)	
1	2	3	4	5	6	7	8	9
Sengaon	896	47	814	782	32	777	29	2010-11
Hingoli	928	49	805	773	32	761	30	2010-11
Aundha (Nagnath)	694	43	657	624	33	602	31	2010-11
Kalamnuri	1197	51	1063	1031	32	985	29	2010-11
Basmath	1017	58	975	935	40	917	38	2010-11
<b>Total</b>	<b>4732</b>	<b>248</b>	<b>4314</b>	<b>4145</b>	<b>169</b>	<b>4042</b>	<b>157</b>	

Source :

'Sub Engineer (Mech.) Mechanical Section, Zilla Parishad, District Ground Water Survey Agency, Water Supply Division Zilla Parishad / Municipal Council/ Municipal Corporation'

Navigation Path :

www.mahasdb.maharashtra.gov.in > Home > Hingoli > Irrigation And Flood Control > Reports

This report should be updated within 2 months after completion of Reporting period  
Data as on May 9, 2013 on SDB