

**Information on Tube wells, Hand pumps and Electric pumps**

Report : Yearly

District : Thane

Reporting Year : 2010-11

Taluka	Current Year					Year Ending		Reference Year
	Total BoreWells (Numbers)	Of Which High Capacity BoreWells (Numbers)	Successful BoreWells (Numbers)	Installed HandPumps (Numbers)	Installed ElectricPumps (Numbers)	Working HandPumps (Numbers)	Working ElectricPumps (Numbers)	
1	2	3	4	5	6	7	8	9
Talasari	20	0	12	12	0	502	6	2010-11
Dahanu	33	0	28	28	0	515	0	2010-11
Vikramgad	27	0	19	19	0	297	0	2010-11
Jawhar	4	0	2	2	0	56	0	2010-11
Mokhada	4	0	4	4	0	53	0	2010-11
Vada	53	0	38	38	0	715	14	2010-11
Palghar	31	0	30	30	0	857	8	2010-11
Vasai	5	0	4	4	0	389	7	2010-11
Thane	0	0	0	0	0	0	0	2010-11
Bhiwandi	20	0	20	20	0	751	25	2010-11
Shahapur	27	0	21	21	0	643	10	2010-11
Kalyan	8	0	6	6	0	179	6	2010-11
Ulhasnagar	0	0	0	0	0	0	0	2010-11
Ambarnath	20	0	18	18	0	207	4	2010-11
Murbad	46	0	37	37	0	526	12	2010-11
<b>Total</b>	<b>298</b>	<b>0</b>	<b>239</b>	<b>239</b>	<b>0</b>	<b>5690</b>	<b>92</b>	

Source :

'Sub Engineer (Mech.) Mechanical Section, Zilla Parishad, District Ground Water Survey Agency, Water Supply Division Zilla Parishad / Municipal Council/ Municipal Corporation'

Navigation Path :

www.mahasdb.maharashtra.gov.in > Home > Thane > Irrigation And Flood Control > Reports

This report should be updated within 2 months after completion of Reporting period

Data as on May 9, 2013 on SDB